

THE 2019 AVALANCHE CYCLE IN COLORADO

An Engineer's Perspective

STORY AND PHOTOS BY CHRIS WILBUR

Avalanche professionals working on land-use planning, mapping, and avalanche defenses must quantify the runouts, extents and flow parameters for long-return period avalanches. Such events are, by definition, rare. They might not occur during our careers. Yet in March of 2019, we witnessed an unprecedented avalanche cycle in Colorado. The series of storms and large avalanches provides us with a unique opportunity to do a reality check on our understanding of these rare events. It also allows us to review the indirect assessment methods that we rely upon. As we begin to reflect, collect data, analyze and discuss our experiences and opinions, several common topics come up.

RETURN PERIODS

What were the average return periods (annual exceedance probabilities) of these large, long-running and destructive avalanches? The data are still coming in, so answers to this question are speculative. That said, based on timber destruction and a review of historic records, it appears that there were dozens of 100-year avalanches. There were probably a few 300-year avalanches too. Not all paths ran big, so the distribution of return periods covers a wide spectrum, but the spectrum was shifted towards lower frequency events compared to most years.

Colorado's documented avalanche history suggests that the 2019 avalanche sizes and runouts, as well as transportation impacts and infrastructure damages, have not been seen since 1906 or earlier. The extent of forest destruction also suggests that many avalanche paths expanded their lateral and distal trim lines into areas not reached in more than a century. Statewide, the big avalanche cycles of 1962, 1986, 1995, and 2003 were clearly exceeded. Newspaper accounts and dendrochronology take the record back farther and include big avalanche cycles in 1891, 1899, and 1906. In the San Juan Mountains of southwest Colorado, the avalanches of 1906 and previous years appear more similar in scale and extent to the March 2019 avalanches than subsequent big avalanche years. Application of dendrochronology methods promises to shed more light on return periods as new data are collected and studied.

RELEASE CHARACTERISTICS

had included up to 12-inches of SWE. The slab releases were unusually dense and strong enabling fracture propagations that extended long distances and probably transmitted fractures deep into the older snow. The result was impressive fracture lines crossing terrain features that usually confine release widths. Many avalanches had crowns extending thousands of feet with some over a mile long. The second unusual characteristic was that avalanches ran on all aspects. Our prevailing westerly winds and snow structure tend to favor releases on the E-NE segments of the compass. In 2019, all aspects were represented with some impressive west- and south-facing avalanches.

FLOW REGIMES

Most of the large avalanches were dry and cold enough to become highly fluidized. In other words, the flow was granular with no free water and plenty of air space between particles, so internal friction was low. The combination of large release volumes and low friction resulted in long runouts and very tall fluidized or saltation layers, as evidenced by damage to surviving large conifers in the paths. The unusually high saltation layers snapped large healthy trees near ground level and uprooted other trees, leaving behind craters.

DAMAGE AND THE D-SCALE

The real indicator of an unusual avalanche season is the extent of damage inflicted. The Colorado Avalanche Information Center (CAIC) reported that ten homes or cabins were damaged or destroyed in six counties (Hinsdale, San Juan, Ouray, Gunnison, Summit, and Pitkin). Two structures were occupied, yet there were no residential avalanche fatalities. Utilities, including major electric and gas infrastructure, were damaged in five counties. Transportation routes were severely impacted. Fortunately, there were no fatalities, even in full vehicle burials on Highway 91 south of Copper Mountain.

We had the opportunity to apply the high end of the D-scale in 2019. The destructive size or D-scale was developed in Canada and is widely used along with the relative or R-scale, developed in the United States, to describe avalanche sizes. Both the D-scale and R-scale use five size categories. The CAIC reported over 80 D4 avalanches. There were at least three D5s, including the Highlands Ridge (Conundrum Creek) and Garrett Peak in Pitkin County, and the Copper Creek in Hinsdale County. It is likely that more D5s will be discovered away from civilization.

The D-scale was developed to use easily observable criteria including mass, path length, and destructive potential. The de-



long-running and destructive avalanches? The data are still coming in, so answers to this question are speculative. That said, based on timber destruction and a review of historic records, it appears that there were dozens of 100-year avalanches. There were probably a few 300-year avalanches too. Not all paths ran big, so the distribution of return periods covers a wide spectrum, but the spectrum was shifted towards lower frequency events compared to most years.

Colorado's documented avalanche history suggests that the 2019 avalanche sizes and runouts, as well as transportation impacts and infrastructure damages, have not been seen since 1906 or earlier. The extent of forest destruction also suggests that many avalanche paths expanded their lateral and distal trim lines into areas not reached in more than a century. Statewide, the big avalanche cycles of 1962, 1986, 1995, and 2003 were clearly exceeded. Newspaper accounts and dendrochronology take the record back farther and include big avalanche cycles in 1891, 1899, and 1906. In the San Juan Mountains of southwest Colorado, the avalanches of 1906 and previous years appear more similar in scale and extent to the March 2019 avalanches than subsequent big avalanche years. Application of dendrochronology methods promises to shed more light on return periods as new data are collected and studied.

RELEASE CHARACTERISTICS

The release characteristics of the March 2019 avalanches exhibited two important characteristics. First, a nearly perfect sequence of weather events created a strong mid- to upper-snowpack structure on top of our usual basal facets. This oversimplified two-layer stratigraphy was mostly able to support gradual loading from December through February. Then the weight of the March storms with SWE increases ranging from 3 to 7 inches in a few days overstressed the strong snowpack. Storm slabs built up over 10-12 days

could enough to become highly fluidized. In other words, the flow was granular with no free water and plenty of air space between particles, so internal friction was low. The combination of large release volumes and low friction resulted in long runouts and very tall fluidized or saltation layers, as evidenced by damage to surviving large conifers in the paths. The unusually high saltation layers snapped large healthy trees near ground level and uprooted other trees, leaving behind craters.

R-scale, developed in the United States, to describe avalanche sizes. Both the D-scale and R-scale use five size categories. The CAIC reported over 80 D4 avalanches. There were at least three D5s, including the Highlands Ridge (Conundrum Creek) and Garrett Peak in Pitkin County, and the Copper Creek in Hinsdale County. It is likely that more D5s will be discovered away from civilization.

The D-scale was developed to use easily observable criteria including mass, path length, and destructive potential. The de-



icebreaker

women's and men's 260 Tech Top

Layer up naturally this season with icebreaker merino.

SNOW SCIENCE

over the past two decades. Avalanche practitioners have observed and predict greater overall snowpack stability as a result of warming. Interestingly, practitioners are predicting more avalanches from upper elevation zones and fewer at low elevations. The snowpack structure and loading that Colorado experienced in 2019 were not inconsistent with climatic trends of warmer and wetter air masses colliding with our mountains. Looking forward, it will be interesting to see how climate change affects avalanches in Colorado and elsewhere.

DATA AND OPPORTUNITIES

The 2019 avalanches in Colorado provide us with an incredible opportunity to improve our understanding of rare events. Today we have tools and resources that were unimaginable the last time an avalanche cycle this big occurred. We have weather instruments, satellite images, UAVs (drones), dynamics models, LiDAR, Google Earth, and more. In just one or two generations, we have gone from sparse data to data overload. This is a good problem to have, but it will take time to analyze and digest all of the information. Ultimately, we will learn a great deal from the 2019 Colorado avalanche cycle.

ACKNOWLEDGMENTS

This article is based on presentations made in 2019 at CSAW and 4SAW by Art Mears and Chris Wilbur, respectively. The author is grateful for the mentorship and guidance of Art Mears, but accepts full responsibility for the content, opinions, and any errors. ●

REFERENCES

Armstrong, Betsy R., *Century of Struggle Against Snow: A History of Avalanche Hazard in San Juan County*.



Several large avalanches occurred in remote areas like this one on Elk Creek in the Weminuche Wilderness in southwest Colorado.



will be interesting to see how climate change affects avalanches in Colorado and elsewhere.

DATA AND OPPORTUNITIES

The 2019 avalanches in Colorado provide us with an incredible opportunity to improve our understanding of rare events. Today we have tools and resources that were unimaginable the last time an avalanche cycle this big occurred. We have weather instruments, satellite images, UAVs (drones), dynamics models, LiDAR, Google Earth, and more. In just one or two generations, we have gone from sparse data to data overload. This is a good problem to have, but it will take time to analyze and digest all of the information. Ultimately, we will learn a great deal from the 2019 Colorado avalanche cycle.


ACKNOWLEDGMENTS

This article is based on presentations made in 2019 at CSAW and 4SAW by Art Mears and Chris Wilbur, respectively. The author is grateful for the mentorship and guidance of Art Mears, but accepts full responsibility for the content, opinions, and any errors. ●

REFERENCES

- Armstrong, Betsy R., "Century of Struggle Against Snow: A History of Avalanche Hazard in San Juan County, Colorado", prepared by, Institute of Arctic and Alpine Research, for San Juan County in 1976, published as Occasional Paper No. 18 by INSTAAR "Overall Hazard Map", prepared by INSTAAR for San Juan County in 1976.
- Armstrong, Betsy R., "Avalanche Hazard in Ouray County, Colorado, 1877-1976, San Juan Avalanche Project, Institute of Arctic and Alpine Research, published as Occasional Paper No. 24, 1977.
- Lazar, Brian, 2018-19 Avalanche Center Summaries, Colorado Avalanche Information Center, *The Avalanche Review*, 38.1, October 2019.
- Martinelli, Jr. M. and Leaf, Charles F., *Historic Avalanches in the Northern Front Range and the Central and Northern Mountains of Colorado*, USDA Forest Service, Rocky Mountain Research Station, General Technical Report RMRS-GTR-38, 1999.
- McClung, D. and Schaerer, P., 1980. *Snow Avalanche Size Classification*. Proceedings ISSW 1980. International Snow Science Workshop, Vancouver BC, Canada, 29 November 3-5, pp. 12-30.
- Wilbur, Chris and Kraus, Sue, *Looking to the Future: Predictions of Climate Change Effects on Avalanches by North American Practitioners*, Proceedings ISSW 2018, International Snow Science Workshop, Innsbruck, Austria.

Chris Wilbur is an avalanche defense engineer based in Durango, Colorado. He is fascinated with the engineering behavior of highly variable complex natural materials, as well as the dynamic response of structures to avalanche loads.



Several large avalanches occurred in remote areas like this one on Elk Creek in the Weminuche Wilderness in southwest Colorado.



This concrete splitting wedge avalanche diversion structure designed by Art Mears saved this home in the Conundrum Creek valley south of Aspen.

scription category is subjective, but the easiest to envision and is the essence of the D-scale. The path length was intended by the authors as an observable substitute for maximum (terminal) velocity. In the engineering world, impact pressure is an important parameter, but it must be calculated using velocity squared and density. Since density has a narrow range and velocity is squared, impact pressures are largely determined by velocities. Assuming a density range of 200–300 kg/m³ suggests that D5 avalanches have maximum velocities of about 60–70 m/s (130–160 mph) and D4s have velocities of about 40–50 m/s (90–110 mph). Many of the March 2019 avalanches were between these velocities and some were probably closer to D5 than D4.

The mass column of the D-scale is also important, since it influences the extent and runout limits. Along with terrain, release mass and entrainment are important factors in determining avalanche damage potential. This connection between total mass and destructive potential is very apparent in applying dynamics models.

Forest destruction is another category on the D-scale. A D5 avalanche can destroy 40 hectares (100 acres) of forest and a D4 can destroy 4 hectares (10 acres). The forest destruction in March 2019 will be useful in further quantifying the number of D4 and D5 avalanches from satellite images.

Prior to 2019, the use of D5 was pretty much unheard of in Colorado. Our avalanche starting zones tend to be limited by ridges and other terrain features. Furthermore, the D-scale descriptors of "largest avalanches known" and "could destroy a village" discourage the use of D5 anywhere in the U.S. outside of Alaska and possibly on large volcanoes of the Pacific Northwest. The identification of at least three D5 avalanches further confirms that March 2019 was a truly historic avalanche period.

CLIMATE CHANGE

The causal factors that led to the big Colorado avalanches of 2019 are complex and cannot be directly tied to a changing climate. However, we have observed and measured warmer winter storms with higher rain-snow elevations